



EXISTING LANDSCAPE
CONDITIONS & CHARACTER


NUMBER DESCRIPTION

- 1 Historic Garden Entry
- 2 Former Garden with Spruce Hedge, Stone Paths & Fountain
- 3 Bridge & Stream
- 4 Yellowwood Slope & Evergreens
- 5 Sugar Maple Row, Former Playhouse Site
- 6 Obstructed Pond View
- 7 Park & Residential Confusing Interface
- 8 Historic Drive Tree Allée
- 9 Historic Drive Stone Entry Piers
- 10 Sugar Maple Dominant Transitional Woods with Sweet Gum
- 11 Historic Stone Gazebo Foundation
- 12 White Oak Dominant Woods
- 13 Planted Rhododendron Cluster
- 14 Fern Patch
- 15 Historic Stone Steps & Bridge Abutment
- 16 Limestone Geology & Rock Outcrops
- 17 Downhill Stream View & Groundcover
- 18 Historic Cobble Gutter

LETTER DESCRIPTION

- A White Spruce Hedge
- B Yellowwood
- C Sugar Maple Woodland
- D Historic Mixed Tree Allée
- E American Linden Area
- F White Oak Upland
- G Sugar Maple Woodland

- - - Property Boundary
- Stream/Water Feature
- Walking Trail, approximate path



Madison Lewis Woodlands
Cultural Landscape Report
Warwick, New York

Client:
 Village of Warwick, NY
 77 Main St.
 Warwick, NY 10990

Landscape Architect:
HERITAGE
LANDSCAPES
 Preservation Landscape Architects & Planners

501 Lake Road
 Charlotte, VT 05445
 802.425.4330
 34 Wall Street
 Norwalk, CT 06850
 203.852.9966

This drawing is the property of Heritage Landscapes and is not to be reproduced or copied in whole or in part. It is only to be used for the project and site specifically identified herein and is not to be used on any other project. It is to be returned upon request.
 © Heritage Landscapes

Drawing Title:
2008 Existing
Conditions Plan

Date:
August 2008

Drawing Number:
EC-2008